DIRECT FIX

Window Profile view: Head B



In very high and extra high wind zones, sealant must be installed between underside of head flashing and top edge of window head flange. — see E2/AS1 Fig. 71(c)

DIRECT FIX

Window Profile view: Sill B



* Alternative solution is the Smartclad 88x34 or 42x34 facing boards which require no pre-cut scriber.

© COPYRIGHT 2017

SMARTCLAD™
The intelligent timber weatherboard

DIRECT FIX

Window Front view: Head B



DIRECT FIX

Window Front view: Sill B



© COPYRIGHT 2017

SMARTCLAD™
The intelligent timber weatherboard